

from Ryan Gottshell  
3/26/2019 Meeting

<b>Date</b>
3/23/1977
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
paul Serfoss

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>March 23 1977</p> <p>Water sample number 2137 taking at discharge Point as located on the Rock Hill property map dated April 28th 1972. Water cloudy.</p> <p>Topsoil and subsoil minimum amount available the diabase crops as huge boulders</p> <p>Prior to starting the top lift, a road will be constructed for the drill Etc and the operator plans to attempt constructing a diversion ditch above the Hill in conjunction with building the access road.</p> <p>Enter no combustible material permitted within 25 ft of magazines</p> <p>Enter third live started, a 25 foot bench is to be maintained between successive faces 50 foot high walls</p> <p>Water sample number PS2 137 submitted to the Harrisburg laboratory for analysis, if the sample does not meet the water quality standards this operator is to be charged with the violation</p>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cu</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
12/9/1977
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>1. Water sample number PS 2160 taken from same location as water sample number PS 2137. Water cloudy.</p> <p>2. A horizontal bench at least 25 ft in width shall maintain between successive phases where multiple benching is required. No combustible material permitted within 25 feet of the magazines explosive storage enter enter erosion must be controlled, desilting facilities should be monitored on a regular basis. As noted water sample number PS 2160 was cloudy.</p> <p>3. Broken Window on Power Shovel cab is to be replaced properly t366 is a private road on General trust own property.</p> <p>Inspectors recommendations: Water sample number PS2 160 has been submitted to the Harrisburg</p>

<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
Paul Serfoss

laboratory for analysis. If the sample does not meet water quality standards this operator is to be charged with the violation note sample number PS2 137 suspended solids were recorded of 46

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
7/18/1978
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
54
<b>INSPECTOR NAME</b>
Paul Serfoss

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>July 18th 1978  Water clear at discharge Point located near RR switch Industrial Waste permit number 0971205 covers this operation.</p> <ol style="list-style-type: none"> <li>1. Several Acres of storage yard is located outside the permitted area.</li> <li>2. The settlement control pond located adjacent to pond# 6 is filled with silt.</li> <li>3. Map number five of 6 shows 50-foot benches.</li> <li>4. Operator to check location of waste dump, must be located on permitted area.</li> </ol> <p>Conditions noted under 1, 2, 3 and 4 to be corrected within 30 days</p> <p>Inspectors recommendations. Is Industrial Waste permit number 0971205 a part of this MDP and enforced by Bureau of surface mine reclamation? If so should the district number 54 inspector have a copy? The operator has 30 days to correct the above noted site problems no central office action necessary at this time.</p>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
9/7/1978
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
Paul Serfoss

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 7th 1978 Remarks. Water clear at point of discharge near the railroad switch. 1. Corrected property maps were submitted by the operator showing the addition to the storage yard. 2. The sediment control pond located adjacent to # 6 has been cleaned out, depth is unknown. 3. Waste dump, dumping has not been discontinued. I question the reason? Broken Window on Mac b-42 left side driver side is to be replaced immediately. Broken windshield on cat 988 and loader left side of split windshield to be replaced promptly.  Inspectors recommendations. No action necessary. Correction work will be checked by the inspector.

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
5/7/1979
<b>Company</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
May 7th 1979 Discharge at railroad switch is clear . Test hole in Woods has been plugged. "Mining Plan" property map shows of future limit of mining as elevation 464 feet. The existing the diversion ditches as shown on the mine

The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>Mine Inspection no</b>
54
<b>INSPECTOR NAME</b>

drainage plan are in need of upgrading - repair etc. The South and Southeast area to be reviewed by the operator.

The #6 basin is again filling up with silk and should be cleaned out before the discharge is affected adversely.

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>



<b>Date</b>
8/15/1979
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
August 15th 1979 Repair windshield on utility pickup truck. Discharge located near railroad switch is clear. File request for an exception to mine a 90 foot high wall within 30 days. 90 foot high wall located between access road to Quarry and the access road to the explosive magazines. Note operator is really affecting an area mined prior to jan 1 1972.
Sedimentation control facilities needed near the East End dump site. The number six Basin is to be cleaned out promptly. Loose rock on East Side High wall has been removed.
Inspectors recommendations: No action necessary at this time. The operator is in process of making Corrections.

May-54
<b>INSPECTOR NAME</b>
Paul Serfoss

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
3/29/1982
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
March 29th 1982 <b>Plant still not operating</b>  Front end loader working in stockpile area.  <b>Water in pit sump clear. 40 foot deep. Not pumping</b>  I found no S&E control problems

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>

--

--

--

--

--

efuse approved:
-----------------

<b>Date</b>
6/7/1982
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
June 7th 1982 Front end loader loading from stock. Crusher not yet operating.  <b>Water in pit sump clear. Not pumping. Very little change in depth. I found no problems with S&amp;D controls. There has been some stripping since last inspection</b>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>efuse approved:</b>

<b>Date</b>
9/28/1982
<b>Company</b>
The General Crushed

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 28th 1982 <b>Plant still down. Water in pit sump Rising, not pumping. I found no s any problems</b>

Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
11/26/1982
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
November 26th 1982 There was no one on site at time inspection 8:30 a.m. to 11:30 a.m. . Not pumping Dash Water Rising? I found no S & E problems

<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>

<b>Date</b>
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
<b>INSPECTOR NAME</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>refuse approved?</b>



<b>Date</b>
2/16/1983
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>mine inspection no</b>
54
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 16th 1983 <b>Quarry close lack of business.</b> <b>Stone remaining in stock not being sold at present</b> License number Supply from main office. Dynamite number 1617 Cap storage number 1616 License to purchase number 1770 Enter inspectors recommendations. 5 - 5A - 5A2 all closed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
<b>Method of mining</b>

<b>Highwalls</b>
<b>total acres permitted</b>

<b>length x width of cut</b>
<b>Condition and use</b>

<b>Regraded</b>
<b>Reclaimed</b>

<b>contract miner?</b>
<b>blasting at site?</b>
<b>auger permit?</b>
<b>efuse approved?</b>

<b>Date</b>
6/21/1983
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
June 21st 1983 <b>Water in pit sump covers bottom level.</b> I found no E&S problems. <b><u>Asphalt plant removed.</u></b> <b>Stone on stock piles.</b> <b>Office manager only one on site.</b>

7974SM1
mine inspection no
54
INSPECTOR NAME
Jonas Carpenter

--

GENERAL INFORMATION
---------------------

Seams
Method of mining

Highwalls
total acres permitted

length x width of cut
Condition and use

Regraded
Reclaimed

contract miner?
blasting at site?
auger permit?
refuse approved?

Date
7/28/1983
Company
The General Crushed Stone Co
LOCATION
East Rockhill Bucks County
MINING PERMIT NO
7974SM1
mine inspection no
54
INSPECTOR NAME
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
July 28th 1983 <u>Quarry not operating.</u> Material removed from stock since last inspection. Water in pit clear. I found no settlement and erosion problems.

--

Seams
-------

Highwalls
-----------

length x width of cut
-----------------------

Regraded
----------

contract miner?
-----------------

**GENERAL INFORMATION**

Method of mining

total acres permitted

Condition and use

Reclaimed

blasting at site?  
auger permit?  
efuse approved?

<b>Date</b>
10/4/1983
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>inspector no</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>October 4th 1983</p> <p><u>Not operating Quarry - loading from stock</u></p> <p><u>Have Bill check mdp acreage</u></p>

**GENERAL INFORMATION**

**Seams**  
diabase

**Method of mining**  
when crushing,  
now selling stock

**Highwalls**  
5 benches 250 ft

**total acres permitted**  
103

**length x width of cu**  
1500x975

**Equip Condition/use**  
loaders, 1 junk  
shovel

**Regraded**  
0

**Reclaimed**  
0

**contract miner?** N

**blasting at site?** N

**auger permit?** N

**efuse approved?** N

<b>Date</b>
12/2/1983
<b>Company</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>December 2nd 1983</p> <p><u>There is no crushing at this Quarry. There has been none for quite some time.</u></p> <p><u>The only activity at present is loading Stone from stock.</u></p>

The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>inspector no</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<u>The bottom left of the Quarry is now covered with water over 50 ft.</u> I found no settlement and erosion problems.
---------------------------------------------------------------------------------------------------------------------------

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
stone quarry

<b>Highwalls</b>
5 benches 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x775
<b>Equip Condition/used</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
11/2/1984
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>inspector no</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
November 2nd 1984 <b>Water and pit approximately 85 ft. This means that two levels will be underwater soon.</b>  There is still quite a bit of stone surage pile.

4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
quarring

<b>Highwalls</b>
5 lifts 250ft
<b>Total acres permitted</b>
103

<b>length x width of cut</b>
1500x775
<b>Equip Condition/used</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
12/4/1985
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>inspector no</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
December 4th 1985 <u>There has been no mining at this point at this mine since 1980.</u> Every year material is loaded from stock to keep permit active. There is some stripping in progress but no mining. The water in pit is now 2 1/2 levels deep approximately 125 ft and still Rising. No pumping or blasting since 1980. ID sign posted. I found no problems with sediment and erosion

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>

<b>Highwalls</b>
5 levels 250 ft
<b>Total acres permitted</b>

<b>length x width of cut</b>
1500x775
<b>Equip Condition/used</b>

<b>Regraded</b>
0
<b>Reclaimed</b>

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>

quarring

103

front end loader -  
good

0

refuse approved: N

<b>Date</b>
7/24/1986
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>inspector no</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
July 24th 1986 <b>The crusher or Quarry operation at this site has not operated since 1980.</b> <b>Water continues to accumulate in pit</b> <b>Third level over half filled</b> They have removed over 500 ton from stock this year to keep permit active. There was a fault in berm in back of crushing plant which was repaired when the inspection was conducted. I.D. posted. I found no problems when inspection was completed.

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
quarring

<b>Highwalls</b>
250ft 5 levels
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x77510
<b>Equip Condition/use</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved: N</b>

<b>Date</b>
10/30/1986
<b>Company</b>
The General Crushed

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
October 30th 1986 Meeting with e Snyder, V Snyder, t demasi, all of General crushed stone to discuss operation of this mine. They State they will keep operational active by removing a minimum of 500 tons of material per year. Section number 2 of Act 2-19 -active operations and minerals

Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>inspector no</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
quarring

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x775
<b>Equip Condition/use</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
9/23/1987
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 23rd 1987 <b>This mine has not operated in years and there has been no blasting.</b> Enter water level in pit has not changed in my opinion. There are no problems with sediment and erosion controls at present. ID sign posted.

<b>inspector no</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
quarring

<b>Highwalls</b>
5 levels 250 ft
<b>Total acres permitted</b>
103

<b>length x width of cut</b>
1500x775
<b>Equip Condition/used</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
2/1/1988
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 1st 1988 Violation. Sediment and erosion berm removed by others to permit ATV to enter permitted area which is causing eminent Danger. Noted this is caused by others but more care must be taken to keep them out.  To remove violation operator to correct berm break and Place Large Stow on outside of entrance to keep a ATV out. Better blockage to be installed at entrance roads. Operator given until February 11th 1988 to correct problem. ID sign in place.

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase

<b>Highwalls</b>
5 levels 250 ft

<b>length x width of cut</b>
1500x775ft

<b>Regraded</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>



**GENERAL INFORMATION**

**Method of mining**  
Quarring

**Total acres permitted**  
103

**Equip use/condition**  
F.E.L.

**Reclaimed**  
0

**Auger permit? N**  
**Refuse approved? N**

<b>Date</b>
8/17/1988
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
August 17th 1988 <b>They have done no mining or blasting at this site for 5 or 6 years.</b> <b>Water in pit now 130 ft deep. They do not pump.</b> This company removes 500-ton from stock per year to keep permit active. The stockyard has telephone poles stored on it. Enter I did not find any problems with sediment and erosion controls. ID sign posted

**GENERAL INFORMATION**

**Seams**  
diabase

**Method of mining**  
Quarring

**Highwalls**  
5 levels 250 ft

**Total acres permitted**  
103

**Length x width of cu**  
1500x775ft

**Equip use/condition**  
F.E.L.

**Regraded**  
0

**Reclaimed**  
0

**contract miner? N**  
**blasting at site? N**  
**Auger permit? N**  
**Refuse approved? N**

<b>Date</b>
7/18/1989
<b>Company</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
July 18th 1989 <b>Plant has not worked for years. There has been no blasting at this site.</b>

The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

Operator removes 500 tons of stock material a year to keep permit active.

F.E.L. on site.

In the opinion of the inspector water level has Rose approximately 5 feet from last inspection now it is in proximately 140 feet deep. I found note Summit and erosion problem. ID sign posted.

Operator advised of Trail bikes and horseback Riders on site this is a dangerous condition.

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x775ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
3/3/1990
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
March 3rd 1990 Inspection with F sentz, jr inspector supervisor. Field Review of Permit Conditions.
No one on site Copy Mailed

4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x915 ft
<b>equip use/condition</b>

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
8/22/1991
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
August 22nd 1991. Inspection with f. Sentz. To discuss wetland in stockpile area

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>

<b>length x width of cut</b>
1500x915 ft
<b>equip use/condition</b>

<b>Regraded</b>
0
<b>Reclaimed</b>

<b>contract miner? N</b>
<b>blasting at site? y</b>
<b>none since 1982</b>

open pit quarry

103

F.E.L.

0

auger permit? N  
refuse approved? N

<b>Date</b>
2/10/1992
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 10th 1992. <b>Not operating.</b> No settlement and erosion problems found. Depth of water 147 ft.

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x915 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
none in years
<b>auger permit? N</b>
<b>refuse approved? N</b>
<b>auger permit? N</b>
<b>refuse approved? N</b>

**Date**

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
August 20th 1993

8/20/1993
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

Water in Quarry has raised another 5 ft or more. No permit problems observed

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x915 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
11/9/1994
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1

**REMARKS COMMENTS AND RECOMMENDATIONS**

November 9th 1994  
 Water still Rising.  
 Tenant on site

7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x900
<b>equipment use/condition</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
none
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
11/9/1994
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
November 9th 1994 Water in Quarry has raised another 5 ft or more. No permit problems observed

--

<b>Seams</b>
--------------

<b>Highwalls</b>
------------------

<b>length x width of cut</b>
------------------------------

<b>Regraded</b>
-----------------

<b>contract miner? N</b>
--------------------------

**GENERAL INFORMATION**

diabase
<b>Method of mining</b>
open pit quarry

5 levels 250 ft
<b>total acres permitted</b>
103

1500x915 ft
<b>equip use/condition</b>
F.E.L.

0
<b>Reclaimed</b>
0

<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>efuse approved?</b> N

<b>Date</b>
9/12/1995
<b>Company</b>
The General Crushed Stone Co
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 12th 1995. Gate locked at Railroad. No one on site. Enter no problems observed. Copy Mailed

**GENERAL INFORMATION**

Seams
diabase
<b>Method of mining</b>
open pit quarry

Highwalls
5 levels 250 ft
<b>total acres permitted</b>
103

length x width of cu
1500x900 ft
<b>equip use/condition</b>
same

Regraded
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N

<b>Date</b>
1/5/1996

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
January 5th 1996. No one on site.

<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4506
<b>INSPECTOR NAME</b>
Jonas Carpenter

Entrance Road covered by over 2 ft of undisturbed snow. Copy Mailed
------------------------------------------------------------------------

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
to be determined

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
to be determined
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
12/11/1996
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
ID sign posted. Site entrance has gate locked. <b>No one is on site. Garage scale house and other buildings are boarded closed.</b> This site has not been work since 1991 or 1992 as the determined from past inspection reports. Inspector will contact the operator to verify that a minimum of 500 tons of material have been removed from site in order to retain an active status. Water monitoring reports are up-to-date. There is no violation history for the past 2 years



7974SM1
<b>INSPECTOR NO</b>
4505
<b>INSPECTOR NAME</b>
John Ermlid

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
to be determined

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
to be determined
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
6/10/1997
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4505
<b>INSPECTOR NAME</b>
John Ermlid

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>June 10th 1997.</p> <p>ID sign is posted and the permitted area is adequately delineated.</p> <p><b>The site remains idle with no evidence of any recent mining activity.</b></p> <p><b>Entrance gate is locked, access gained on foot.</b></p> <p><b>The pit is completely water filled. All ponds and wash water basins are becoming vegetated and are becoming Wetlands.</b> There are no erosion and sedimentation problems evident. Operator is reminded that a minimum of 500 tons of material must be removed per year to retain an active status. there's no violation in history for the past two years. copy mailed</p>

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
processing plants

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
10/31/1997
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4505
<b>INSPECTOR NAME</b>
John Ermlid

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>October 31st 1997. Gate at railroad lock. No one on site. Copy Mailed</p>

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x900 ft
<b>Condition and use</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
3/25/1998
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
Christian Kula

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>March 25th 1998.</p> <p>ID sign is posted and the permitted area is adequately delaminated.</p> <p><b>The site is in idle. Entrance gate is locked.</b></p> <p><b>The Pitt remains water-filled. Basins are vegetated.</b></p> <p>There are no erosion and sediment problems evident there has been no violation history for the past 2 years.</p> <p>Copy Mailed</p>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cut</b>
1500x900 ft
<b>Condition and use</b>
processing plants

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>efuse approved?</b> N

<b>Date</b>
9/30/1998
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>September 30th 1998.</p> <p><b>1. inspection was conducted solo.</b></p> <p><b>2. The Quarry was not operating during this inspection. There were no stock piles or processing of Stone observe.</b></p> <p><b>3. A small gate was locked at the entrance preventing automobile entrance.</b></p> <p><b>4. The water elevation in the pit appears to be high. Milestone materials should keep an eye on the water level of this pit to prevent overflow or possible flooding.</b></p> <p><b>5. Signs warning people of Quarry high wall are sparse. More signs warning people of the high wall danger</b></p>

<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
christiam Kula

should be posted.

6. There was no physical barriers preventing an unknown trespasser from assessing high wall. Milestone materials should submit a plan to the dep which discusses how this Danger will be prevented. The trail which goes around the Pitt appeared to be travel frequently by hikers horses and mountain bike riders, a campsite was also deserved a long the high wall.

7. Milestone materials is reminded that a minimum of 500 tons a year a mineral material must be sold to keep the permit active. I observed no stock piles of material on site . Milestone materials should submit to dep documentation justifying the sales for 1998 and contact me when any future sales are to take place. I would like to be on site when the next shipment of material is to leave the site. Copy mailed to Tim

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
103

<b>length x width of cu</b>
1500x900 ft
<b>Condition and use</b>
processing plant non operational

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>efuse approved?</b> N

<b>Date</b>
1/7/1999
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
christian Kula

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>January 7th 1999.</p> <p>1. This inspection was conducted solo.</p> <p>2. The Quarry was not operating at time of this inspection.</p> <p>3. Operator ID sign complete with permit number was observed by gate at the West entrance to the Quarry. The gate was locked.</p> <p>4. The gate located at the north entrance to the Quarry was open however Boulders blocked access further up this entrance.</p> <p>5. The elevation of water in the pit appears as though it is being monitored. A wooden stake is located at the entrance exit ramp to the site. The steak appears to Mark the water elevation for the month of November 1998. The water level appears to be down a few inches since November 1998 the pit is full of water.</p> <p>6. I walked the trail that surrounds the Quarry. There was evidence of footprints and tire tracks. Trespassers are still gaining access to this site. Due to the location of this Quarry this is not really preventable however signs warning at the high wall still need to be posted this should be done before April 1st 1999.</p> <p>7. Three pictures of the stockpile area were taken during this inspection. The pictures were taken to help keep track of the stockpile on site. See letter from Milestone materials dated 10 21 1998. Copy to mailed.2/2/199</p>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>Total acres permitted</b>
103

<b>length x width of cut</b>
1500x900 ft
<b>Condition and use</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
2/2/1999
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
christian Kula

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 2nd 1999. Milestone material inc is in violation of section 12, part (U)U. Progress report. SMCRA-1984-219 SECT 12 (U). THE 1998 NON COAL MINEING PRODUCTION SURFACE MINING OPERATIONS ANNUAL REPORT should be submitted to the department immediately

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>Total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>Condition and use</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
5/4/1999
<b>Company</b>
Milestone Material 1900 sullivan trail easton pa
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
christian Kula

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>May 4 1999</p> <p>1. This inspection was conducted solo. The pit is full of water and the crusher does not appear to be operational. Nobody was on site and the gate was locked. A new ID sign is posted listing the new owner Hanson.</p> <p>2. The change in ownership information should be submitted to the department if it hasn't been already. Many private property signs have been posted no violations observed. Copy to be mailed</p>

May A10€

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
same

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
4/25/2001
<b>Company</b>
Hanson Aggregates of pa 1900 sullivan trail easton
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>April 25th 2001</p> <p>1. E&amp;s controls should be upgraded. Water is Flowing from the pit pass the crusher and down the road towards the entrance. The water is bypassing the S&amp;D control measures. This condition should be corrected as soon as possible.</p> <p>2. No activity on site on this date no sign of recent activity.</p> <p>3. ID sign is at the entrance to the site, but has again been knocked down or blown over. Operator should take steps to ensure to sign a secured and posted.</p> <p>4. Gate was open Locke was missing.</p>

7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
christian Kula

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
excavator

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
5/23/2002
<b>Company</b>
Hanson Aggregates of pa 1900 sullivan trail easton
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4556
<b>INSPECTOR NAME</b>
christian Kula

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>May 23rd 2002.</p> <ol style="list-style-type: none"> <li>1. Mining operations at this permit remain idle. The operator is advised at a minimum of 500 tons of material must be mine this year or a request for a temporary cessation must be submitted to the Pottsville District office.</li> <li>2. The operator is advised that the ID sign has been removed from the wooden frame and will need to be replaced. The shine should be visible from the public roadway.</li> <li>3. No E&amp;S control problems noted and there was no discharge from monitoring point 001. Npdes number PA 0594121 to one expires July 19th 2003.</li> </ol>

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
excavator

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
none
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
2/8/2005
<b>Company</b>
Hanson Aggregates of pa 1900 sullivan trail easton
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 8th 2005. The complete inspection was conducted solo. The front gate was locked, so a walking inspection was conducted. Stone was stockpiled on site. Some water was flowing from the impoundment on a road. The discharge was caught in a small depression no other activity was observed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N



<b>Date</b>
4/25/2008
<b>Company</b>
Hanson Aggregates of pa 1900 sullivan trail easton
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
April 25th 2008. The complete inspection was conducted solo. The front gate was locked. One track excavator and One Track Hammer were Idol near garage. No mining activity observed. Signature to mailed.

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
6/5/2008
<b>Company</b>
Hanson Aggregates of pa 1900 sullivan trail easton
<b>LOCATION</b>
East Rockhill Bucks County

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
June 5th 2008. This inspection report is to note a site meeting with Miss Chris Ann Gahagan (regional Environmental manager (Hanson), Bob Melani (Ottsville supervisor\ Hanson), Mr. Mike Menghini ) environmental group manager DEP, Ms. Collen Stutzman (SMCIS/DEP), Mr. Mike Duke (Blasting Inspector) and Amy Bollinger. The meeting was held to discuss the removal of oversized material and possible blasting on site. Ms. Gahagan was asked to submit an updated operations map showing current site conditions (Within the year), a blast plan with a narrative on how blasting will be conducted in a narrative explaining how the oversize will be removed in a direction of mining. The operator is to keep erosion/ settlement controls in mind and notifying

<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

the site inspector should the conditions change. Questions can be directed to Miss Colleen Stutzman at the Pottsville district office 570-621-3118. Signature to mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
7/29/2008
<b>Company</b>
Hanson Aggregates of pa 1900 sullivan trail easton
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
July 29th 2008. The complete inspection was conducted solo. The gate to the site was locked. No activity was observed. Signature to mailed.

Amy Bollinger

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
12/15/2008
<b>Company</b>
Hanson Aggregates of pa 2900 terminal ave
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

**REMARKS COMMENTS AND RECOMMENDATIONS**

December 15th 2008.  
 The complete inspection was conducted solo. The gate to the site was locked. No activity was observed .  
 Signature to be mailed.

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
2/9/2009
<b>Company</b>
Hanson Aggregates of pa 2900 terminal ave
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 9th 2009. The complete inspection was conducted solo the gate to the site was locked. No activity was observed. September 10th 2009. Enter the complete inspection was conducted solo. The gate was unlocked. No activity was observed. Signature to be Mailed.

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cu</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on sit

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>efuse approved: N</b>

<b>Date</b>
9/10/2009
<b>Company</b>
Hanson Aggregates of pa 2900 terminal ave
<b>LOCATION</b>
East Rockhill Bucks County

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
November 2nd 2009. Enter the complete inspection was conducted solo the gate was locked no activity was observed. Signature Mailed

East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
2/1/2010
<b>Company</b>
Hanson Aggregates of pa 2900 terminal ave
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
February 1st 2010. The complete inspection was conducted solo. The gate was unlocked. No activity was observed. Sample 451-9265 was collected.

Amy Bollinger

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
4/21/2010
<b>Company</b>
Hanson Aggregates of pa 2900 terminal ave
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

**REMARKS COMMENTS AND RECOMMENDATIONS**

April 21st 2010  
the complete inspection was conducted solo. The gate was unlocked. No activity was observed.

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
7/12/2010
<b>Company</b>
Hanson Aggregates of pa 2900 terminal ave
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
This complete inspection was completed solo. The Gate was locked. No activity was observed. Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
11/3/2010
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
November 3rd 2010. This inspection was conducted solo. The gate was locked. No activity was observed. Material was removed from near the garage (500 tons).

<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
1/11/2011
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
January 11th 2011. This complete inspection was conducted solo. The gate was locked. No activity was observed. Signature mailed



<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>Total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>Equipment use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
5/4/2011
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
May 4th 2011. This complete inspection was conducted solo. The gate was locked. No activity was observed. Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>Total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>Equipment use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
9/6/2011
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 6th 2011 this complete inspection was conducted solo. The gate was unlocked. No activity was observed. Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
10/27/2011
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
October 27th 2011. Enter this complete inspection was conducted solo. The gate was unlocked. No activity was observed. Signature Mailed

7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>efuse approved?</b> N

<b>Date</b>
1/11/2012
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
January 11th 2012. This complete inspection was conducted solo. The gate was locked. No activity was observed. Signature Mailed

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
7/12/2012
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>July 12th 2012.                  Complete inspection was conducted solo. The gate was locked. No activity was observed.                  Signature Mailed</p>

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

**Date**

**REMARKS COMMENTS AND RECOMMENDATIONS**

11/15/2012
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

November 15th 2012
This complete inspection was conducted solo. One front end loader was loading trucks to remove the required 500 tons. No discharge was observed.
Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
1/25/2013
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
January 25th 2013.
This complete inspection was conducted solo . the front gate was latched but not locked. No activity was observed.
Signature Mailed

7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
6/24/2013
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
June 24th 2013. This complete inspection was conducted solo. The front gate was locked. No activity was observed. Signature Mailed

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
9/12/2013
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 12th 2013. The complete inspection was conducted so low. The front gate was locked. No activity was observed. A bench on the Northside of pit was blasted to deter trespassers. Signature Mailed

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
no equipment on site

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

**Date**

**REMARKS COMMENTS AND RECOMMENDATIONS**

2/20/2014
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

February 20th 2014.  
This complete inspection was conducted solo. The front gate was unlocked. No activity was observed. Site inaccessible due to snow.  
Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
6/2/2014
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
June 2nd 2014. This complete inspection was conducted solo. The front gate was unlocked. No activity was observed. Signature Mailed



7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
9/10/2014
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
September 10th 2014 This complete inspection was conducted in the company of mr. Garry latcha (DEP). The front gate was unlocked. No activity was observed. Signature Mailed

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
12/4/2014
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
December 4th 2014  This complete inspection was conducted solo. No activity was observed.

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
March 31st 2015.

3/31/2015
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

This complete inspection was conducted solo. The exterior gate was locked. No activity was observed. The gate next to the lake was pushed over and mr. Doug Chilson superintendent was contacted.  
Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
6/30/2015
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
June 30th 2015. This complete inspection was conducted solo. The exterior gate was locked. No activity was observed. Signature Mailed

7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
8/24/2015
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
August 24th 2015. This complete inspection was conducted solo. The exterior gate was locked. No activity was observed. Signature Mailed

--

<b>Seams</b>
--------------

<b>Highwalls</b>
------------------

<b>length x width of cut</b>
------------------------------

<b>Regraded</b>
-----------------

<b>contract miner? N</b>
--------------------------

**GENERAL INFORMATION**

diabase
<b>Method of mining</b>
open pit quarry

5 levels 250 ft
<b>total acres permitted</b>
N/A

1500x900 ft
<b>equip use/condition</b>
F.E.L.

0
<b>Reclaimed</b>
0

<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>efuse approved?</b> N

<b>Date</b>
3/25/2016
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>March 25th 2016.</p> <p>This complete inspection was conducted solo. The exterior gate was locked. Timber was being removed from this site.</p> <p>Signature Mailed</p>

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cu</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>efuse approved?</b> N

<b>Date</b>

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
July 11th 2016

7/11/2016
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

This complete inspection was conducted solo. The exterior gate was locked. Timber was being removed from site.  
Signature Mailed

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
11/14/2016
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
November 14th 2016. This complete inspection was conducted solo. The gates were locked and no activity was observed. Signature Mailed

7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

--

<b>GENERAL INFORMATION</b>
----------------------------

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner? N</b>
<b>blasting at site? y</b>
no recent blasting
<b>auger permit? N</b>
<b>refuse approved? N</b>

<b>Date</b>
3/24/2017
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
March 24th 2017. This complete inspection was conducted solo. The gates were locked and no activity was observed.

--

<b>Seams</b>
--------------

<b>Highwalls</b>
------------------

<b>length x width of cut</b>
------------------------------

<b>Regraded</b>
-----------------

<b>contract miner? N</b>
--------------------------

**GENERAL INFORMATION**

diabase
<b>Method of mining</b>
open pit quarry

5 levels 250 ft
<b>total acres permitted</b>
N/A

1500x900 ft
<b>equip use/condition</b>
F.E.L.

0
<b>Reclaimed</b>
0

<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
6/16/2017
<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>June 16th 2017.                  This complete inspection was conducted solo. The gates were locked and no activity was observed.                  Signature Mailed</p>

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cu</b>
1500x900 ft
<b>equip use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N

<b>Date</b>
9/7/2017

<b>REMARKS COMMENTS AND RECOMMENDATIONS</b>
<p>September 7th 2017.                  This complete inspection was conducted solo. The gates were locked and no activity was observed.</p>



<b>Company</b>
Hanson Aggregates of pa 7660 imperial way
<b>LOCATION</b>
East Rockhill Bucks County
<b>MINING PERMIT NO</b>
7974SM1
<b>INSPECTOR NO</b>
4519
<b>INSPECTOR NAME</b>
Amy Bollinger

Signature Mailed

**GENERAL INFORMATION**

<b>Seams</b>
diabase
<b>Method of mining</b>
open pit quarry

<b>Highwalls</b>
5 levels 250 ft
<b>total acres permitted</b>
N/A

<b>length x width of cut</b>
1500x900 ft
<b>equipment use/condition</b>
F.E.L.

<b>Regraded</b>
0
<b>Reclaimed</b>
0

<b>contract miner?</b> N
<b>blasting at site?</b> y
no recent blasting
<b>auger permit?</b> N
<b>refuse approved?</b> N