

STATE SENATOR  
**STEVE SANTARSIERO**  
16TH SENATORIAL DISTRICT

□ SENATE BOX 203010  
THE STATE CAPITOL  
HARRISBURG, PA 17120-3010  
717-787-7305  
FAX: 717-783-5962

□ 3 TERRY DRIVE, SUITE 201  
NEWTOWN, PA 18940  
215-497-9490

□ 2003 LOWER STATE ROAD  
BUILDING 100, SUITE 121  
DOYLESTOWN, PA 18901  
215-489-5000



Senate of Pennsylvania

**COMMITTEES**

COMMUNICATIONS & TECHNOLOGY,  
DEMOCRATIC CHAIR  
APPROPRIATIONS  
CONSUMER PROTECTION  
& PROFESSIONAL LICENSURE  
JUDICIARY  
LOCAL GOVERNMENT

E-MAIL: [SenatorSantarsiero@psenate.com](mailto:SenatorSantarsiero@psenate.com)  
FACEBOOK: [www.facebook.com/SenSantarsiero](http://www.facebook.com/SenSantarsiero)  
TWITTER: @SenSantarsiero  
INSTAGRAM: @Senator\_SteveSantarsiero  
WEB: [www.senatorstevesantarsiero.com](http://www.senatorstevesantarsiero.com)

June 21, 2019

**Via Email and Regular Mail**

Gary Latsha  
Acting Mining Manager  
PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Pottsville District Mining Operations  
5 West Laurel Boulevard  
Pottsville, PA 17901

Re: Rockhill Quarry

Dear Mr. Latsha,

I am writing to follow up on our discussion at the June 14 meeting at the DEP's Southeast Regional Office in Norristown regarding the historical operation of the Rockhill Quarry (the "Quarry"). At that meeting, Mr. Stefanko stated that it was the Department's position that the Quarry has been in continuous operation since the early 1980s. Based on the information that my office and others have obtained to date, I believe that the Department is incorrect on that point.

The Department's annual state-wide quarry reports show that in two years, 1983 and 1986, fewer than 500 tons of material were removed from the Quarry (*i.e.*, zero tons in 1983 and 180 tons in 1986). Copies of the relevant pages of those reports are enclosed for your convenience.

To date we have not received any underlying documentation pertaining to activity at the Quarry for those years save three 1986 inspection reports signed by a Jonas Carpenter, who appears to have been the Department's inspector at the site until at least early 1996. The July 24, 1986 report states in the comments section that "[the operators] have removed over 500 ton [sic] from stock this year to keep permit active." Similarly, according to the October 30, 1986 inspection report "[t]hey state they will keep operation active by removing a minimum of 500 tons of material per year." Copies of both inspection reports are also enclosed.

It would appear that in both instances the inspector was merely repeating what the operators had told him – without offering him any proof – while he was performing his inspection. We are aware of no documents that would support the claim that the Quarry's operators were in fact removing a minimum of 500 tons of material from the Quarry in either 1983 or 1986. **Indeed, as noted, the Department's own annual reports contradict that assertion.** Please provide us with all evidence supporting the Department's conclusion that the site's operators removed a minimum of 500 tons of material from the Quarry in 1983 and 1986.

For the years 1984, 1987, 1993, 1995 and 1996 there are no annual reports available. There are, however, inspection reports for those years. While the inspection reports list the Quarry as "active" in the operational status box on the forms, they do not mention whether a minimum of 500 tons of material were in fact being removed during those years. On the contrary, the reports have numerous comments which suggest the opposite:

- July 16, 1984 inspection report states "[t]hey have not did [sic] any quarrying in over 2 years – they still have material in stock which they are moving *slowly*." [Emphasis added.]
- November 2, 1984 inspection report states "[t]here is still quite a bit of stone on storage pile."
- September 23, 1987 inspection report states that "[t]his mine has not operated in years and there has been no blasting."
- October 23, 1993 inspection report states "[n]o one on site."
- Each of the inspection reports from 1995 include the notation "[n]o one on site" and three of them note that the gate was locked.
- February 5, 1996 inspection report (the last one that Mr. Carpenter filled out) states "[n]o one on site."
- December 11, 1996 inspection report by John Emlick has the inscription "[a]ctive ??" in the operational status block. The notes section of that report reads, in relevant part that "[s]ite entrance has gate locked. No one on site. Garage, scalehouse and other buildings are boarded closed. This site has not been worked since 1991-2 as determined from past inspection reports. Inspector will contact Operator to verify that a minimum of 500 tons of material has been removed from site in order to retain an active status."

All of these inspection reports are enclosed for your convenience.

Please provide us with all evidence supporting the Department's conclusion that the site's operators removed at least 500 tons of material from the Quarry during these years and, in particular, any information regarding inspector Emlick's attempts to follow up with the Quarry's operator after his December 11, 1996 inspection.

At the June 14 meeting, in response to Congressman Fitzpatrick's question, the Department acknowledged that the site is one of only two quarries in Pennsylvania in which asbestos has been found and, likely, the only one in a residential area. In light of that fact and the potential risk to residents' health and safety that this Quarry represents, it is particularly important that the issues raised here be addressed as quickly as possible. Toward that end, I would ask that the Department provide us with the information we have requested in this letter by July 15, at the latest.

Thank you.

Very truly yours,



Steven J. Santarsiero  
State Senator, 10<sup>th</sup> District

Enclosures

CC (via email w/encls):

Michael Brunelle, Office of the Governor, Chief of Staff  
Will Danowski, Office of the Governor, Secretary of Legislative Affairs  
Congressman Brian Fitzpatrick  
State Senator Bob Mensch  
State Representative Craig T. Staats, Pennsylvania Representative  
Secretary Patrick McDonnell, PA DEP  
Marianne Morano, East Rockhill Township, Manager  
Megan Banis-Clemens, Pennridge School Board, President  
Patrick Patterson, PA DEP, Southeast Regional Director  
Robert Fogel, PA DEP, Southeast Region Local Government Liaison  
Katie Zackon, Rockhill Environmental Preservation Alliance

1983

BUCKS COUNTY

Operators and Mines/ or Mine Drainage Permit No.	Production of Minerals -- Met Tons				Aver- age Days Worked	No. of Em- ployees	Tonnage of Minerals Shipped to			Non- Fatal Acci- dents
	Shipped to Market		Total	Out-of- State Markets			In-State Markets	Foreign Markets	Fatal Acci- dents	
	By Rail	By Water	By Truck							
American Olean Tile Co. 7974SM6	-	-	-	37,164	26	6	-	-	-	-
Better Materials Corp. 7973SM2	-	-	1,268,489	1,217,489	182	21	-	507,395	761,094	1
Edison Quarry 7975SM4	-	-	37,000	35,200	250	5	-	37,000	-	-
The General Crushed Stone Co. 7974SM1	-	-	-	-	-	2	-	-	-	-
Miller Quarries 7973SM3	-	-	388,978	432,198	210	14	-	388,978	-	2
New Hope Crushed Stone Co. 7974SM3	-	-	436,960	462,015	249	13	-	36,960	400,000	-
Silvi Concrete Products, Inc. 5476SM5	-	-	92,000	92,000	152	2	-	92,000	-	-
Warner Co. 7975SM5	-	-	1,289,400	200	30	-	989,400	300,000	-	-
<b>COUNTY TOTAL</b>	-	-	<b>3,512,827</b>	<b>2,276,266</b>	<b>137</b>	<b>73</b>	<b>989,400</b>	<b>1,362,333</b>	<b>1,161,094</b>	<b>3</b>

1986

ROCKS COUNTY

Operators and Mines/ or High Drainage Permit No.	Production of Minerals -- Net Tons				No. of Employees	Thousands of Minerals Shipped to			Fatal Accidents
	Shipped to Market		Total Production of Minerals	In-State Markets		Foreign Markets	Out-of-State Markets	Fatal Accidents	
	By Water	By Truck							
American Glass Tile Company 7974306	0	0	20,725	20,725	18	0	0	0	0
Better Materials Corp. 7974302	0	0	1,564,349	1,564,349	201	0	0	916,913	0
Blossing Glen Quarry 7975281	0	0	570,700	570,700	244	0	0	570,700	0
Colony Materials A17975282	0	0	79,500	79,500	178	0	0	79,500	0
Delaware Quarries 09832601	0	0	2,000	2,000	100	0	0	0	0
Delaware Valley Landscapes 09830301	0	0	82,801	82,801	180	0	0	0	0
G.R.O.S., Inc. 09840501	0	0	0	0	270	0	0	0	0
General Crushed Stone Bx Rail 7974301	0	0	180	180	0	0	0	180	0
H & K Materials 7974305	0	0	456,700	456,700	230	0	0	456,700	0
Langhorne Stone Co. 09832501	0	0	0	0	45	0	0	0	0
M & M Stone Company 7974309	0	0	652,000	652,000	270	0	0	552,000	0
Miller Quarries 7973503	0	0	449,316	449,316	202	0	0	449,316	0
New Hope Crushed Stone & Lime 7974303	0	0	650,000	650,000	250	0	0	75,000	0
Varner Company 7975285	0	0	1,540,000	1,540,000	240	0	0	1,000,000	0
<b>COUNTY TOTAL</b>	<b>0</b>	<b>0</b>	<b>6,068,271</b>	<b>6,068,271</b>	<b>240</b>	<b>0</b>	<b>0</b>	<b>4,099,609</b>	<b>0</b>

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

Mini mit No. 733-5  
Drainage Permit No. 7974SM1  
Mine Inspection No. 54  
Reinspection No. 1-83

Company <u>General Crushed Stone Co</u>	Mine Location: County <u>Becks</u>	Township <u>E Rockhill</u>
Mining Permit Acres Affected <u>95</u>	Drainage Permit Acres Affected	
Status of Operation: Active	Inactive <u>X</u>	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO \_\_\_ NOTED \_\_\_
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO \_\_\_ NOTED \_\_\_
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO \_\_\_ NOTED \_\_\_

REMARKS AND RECOMMENDATIONS:

Quarry closed LACK of BUSINESS -

STONE REMAINING IN STOCK NOT BEING SOLD

AT PRESENT -

License # supplied from MAIN OFFICE

DYNAMITE STORAGE #1617

Cap STORAGE #1616

LICENCES TO PURCHASE #1770

Company Official Contacted <u>Jack P Bower</u>	Title <u>Office Manager, Contractor</u>
Mine Inspector <u>James Carpenter</u>	Inspection Date <u>2-16-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

5-5A-5A2 ALL Closed

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

Mine Permit No. 733-5  
Drainage Permit No. 7974SM1  
Mine Inspection No. JV  
Reinspection No. 2-83

Company <u>GENERAL CRUSHED STONE</u>	Mine Location: County <u>BUCKS</u>	Township <u>E ROCKHILL</u>
Mining Permit Acres Affected <u>95</u>	Drainage Permit Acres Affected	
Status of Operation: Active <u>X</u>	Inactive	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO      NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES V NO      NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO      NOTED

REMARKS AND RECOMMENDATIONS: FRONT END LOADER LOADING FROM STOCK PILE

WATER IN PIT PUMP CHECK - 45' DEEP -

I FOUND NO S + E PROBLEMS

Company Official Contacted <u>Judy W Smergart</u>	Title <u>Dispatcher</u>
Mine Inspector <u>Jones Carpenter</u>	Inspection Date <u>4-28-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

A

F

Mine Permit No. 733-5  
Drainage Permit No. 7974SM1  
Mine Inspection No. 54  
Reinspection No. 3-83

Company <u>General Crushed Stone</u>	Mine Location: County <u>BUCKS</u>	Township <u>E. ROCKHILL</u>
Mining Permit Acres Affected <u>95-3-5.2</u>	Drainage Permit Acres Affected	
Status of Operation: Active <u>X</u>	Inactive <u>X</u>	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO      NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO      NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO      NOTED

REMARKS AND RECOMMENDATIONS: WATER IN PIT Sump Covers  
BOTTOM level-

I FOUND NO S+E Problems

ASPHALT PLANT Removed.

STONE ON STOCKPILES

Office Mgr ONLY ONE ON SITE

Company Official Contacted <u>Joseph P. Brown</u>	Title <u>Office Manager</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>6-21-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:  
none



Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

*C*  
*field*

Permit No. 733-5  
Drainage Permit No. 79745M1  
Mine Inspection No. 54  
Reinspection No. 4-B3

Company <u>General Crushed Stone</u>	Mine Location: County <u>Bucks</u>	Township <u>E Rockhill</u>
Mining Permit Acres Affected <u>95-3-5.2</u>	Drainage Permit Acres Affected	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES  NO  NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES  NO  NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES  NO  NOTED

REMARKS AND RECOMMENDATIONS: QUARRY NOT OPERATING  
MATERIAL REMOVED FROM STOCK SINCE  
LAST INSPECTION  
WATER IN PIT CLEAR  
I FOUND NO S + E PROBLEMS-

Company Official Contacted <u>Joseph P. Burch</u>	Title <u>Office Manager</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>7-28-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

NONE

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

5

low

INSPECTION REPORT

Date 10-4-83

PERMITTEE The General Crushed Stone Company ADDRESS P.O. Box 231 Easton, Pennsylvania 18042	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SMI
TYPE OF INSPECTION Partial <input checked="" type="checkbox"/> Followup <input type="checkbox"/> Complete <input type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. 300732 Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date 1-1-84	Operational Status ACTIVE

A1. GENERAL MINING INFORMATION

- a. Seams BASTARD TRAP ROCK (DIA BASE)
- b. Highwall/s height/s: actual 5 benches 250'  
bonded N/A
- c. Length & Width of cut/s 1500' x 975'
- d. Total Acres: Permitted N/A Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining \_\_\_\_\_ Acres  Unauthorized Mining Activities \_\_\_\_\_ Acres

2. Method of Mining: TRUCK TO CRUSHER WHEN CRUSHING  
NOW SELLING STOCK

3. Equipment: Use & Condition 2 FRONT END LOADERS - good CONDITION  
1 TRUCK SHOVEL

4. Contract Miner Name: \_\_\_\_\_  
 yes  no Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_
- b. Adjudications Outstanding  yes  no Type \_\_\_\_\_
- c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>Joseph Bronico</u> Signature <u>Joseph Bronico</u>	Title <u>O.M.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Investigator <u>James Carpenter</u> Signature		I.D. No. <u>75106</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-4-83

Permit Number <b>7974SM1</b>	Township <b>East Rockhill</b>	County <b>Bucks</b>
Name of Permittee <b>The General Crushed Stone Company</b>		

C. Comments & Recommendations

*NOT OPERATING QUARRY - loading from STOCK*

*Have Bill Check MDP Average*

Operator

*James Brown*  
Signature

*10/4/83*  
Date

Inspector

*James Carpenter*  
Signature



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 12-2-83

Permit Number  
7974SM1

Township  
East Rockhill

County  
Bucks

Name of Permittee  
The General Crushed Stone Company

C. Comments & Recommendations

There is no crushing at this Quarry -  
There has been none for quite some time -  
The only activity at present is loading  
& TOWNE from STOCK -

The BOTTOM LEFT of The Quarry is now  
Covered with WATER over 50'

I Found NO S + E PROBLEMS

Operator

Joseph P. Brown  
Signature

12/2/83  
Date

Inspector

James Carpenter  
Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION  
Non Coal

A

OFFICIAL USE ONLY

INSPECTION REPORT

Date 2-2-84

PERMITTEE The General Crushed Stone Co. ADDRESS P.O. Box 231 Easton, Pa. 18042	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300735</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-84</u>	Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Diorase
  - b. Highwall/s height/s: actual 5 lifts to 259 ft.  
bonded \_\_\_\_\_
  - c. Length & Width of cut/s 1500 X 775 ft.
  - d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
  - e. Phase/s being mined: 7B3
- Unauthorized Mining 0 Acres     Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition SAME

4. Contract Miner  yes  no    Name: \_\_\_\_\_  
Address: \_\_\_\_\_

5. Blasting at Site:  yes  no    Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no    Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no     Active     Inactive     not started     completed

7. Refuse Disposal Approved  
 yes  no     Active (describe)     Inactive

8. Previous Enforcement:
- a. Orders & Agreements outstanding     yes  no    Type \_\_\_\_\_
  - b. Adjudications Outstanding     yes  no    Type \_\_\_\_\_
  - c. Violations on Last Inspection     yes  no    (If yes, explain status in remarks)

Person contacted <u>RICK FRANK</u>	Title <u>GEN SUPT</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Signature <u>Rick Frank</u>	Investigator <u>James Carpenter</u>	<u>45216</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

NONE

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 2-2-84

Permit Number  
7974SM1

Township  
East Rockhill

County  
Bucks

Name of Permittee

The General Crushed Stone Company

C. Comments & Recommendations

1 D Sign posted.

There has been no BLASTING AT THIS SITE for quite some time - There is no explosives kept on site AT present

No water is being pumped -

STEEL PILES ARE standing -

Operator

[Signature]  
Signature

2/2/84  
Date

Inspector

[Signature]  
Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

Non Coal

INSPECTION REPORT

Date 4-4-84  
goc

PERMITTEE The General Crushes Stone Co. ADDRESS P.O. Box 231 Easton, Pa. 18042	TOWNSHIP E. Rockhill	COUNTY Lucks	PERMIT NO. 7974SM1
	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-84</u> Operational Status <u>Active</u>

A1. GENERAL MINING INFORMATION

- a. Seams Diabase
  - b. Highwall/s height/s: actual 250 ft = 5 lifts.  
bonded \_\_\_\_\_
  - c. Length & Width of cut/s 1500 X 775 ft.
  - d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
  - e. Phase/s being mined: 733-1
- Unauthorized Mining 0 Acres     Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition 5 Anvils

4. Contract Miner                      Name: \_\_\_\_\_  
 yes     no                      Address: \_\_\_\_\_

5. Blasting at Site:     yes     no                      Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster     yes     no                      Contractors name \_\_\_\_\_

6. Auger Permit                      Safety Permit No. \_\_\_\_\_  
 yes     no                       Active     Inactive                       not started     completed

7. Refuse Disposal Approved  
 yes     no                       Active (describe)     Inactive

8. Previous Enforcement:
- a. Orders & Agreements outstanding                       yes     no                      Type \_\_\_\_\_
  - b. Adjudications Outstanding                       yes     no                      Type \_\_\_\_\_
  - c. Violations on Last Inspection                       yes     no                      (If yes, explain status in remarks)

Person contacted	Title	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR 5.1 attached.
Signature <u>Jack Frank</u>		Investigator <u>James Carpenter</u> <input checked="" type="checkbox"/> <u>4507</u> Signature                      I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

None



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 4-4-84

Permit Number <u>7974SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
---------------------------------	--------------------------------	------------------------

Name of Permittee  
The General Crushed Stone Company

C. Comments & Recommendations

ID Sign posted

There are no explosive stored at this mine - no blasting since last insp -

The water in the quarry is now appx 65' deep rising on 2nd lift -

Stock piles wearing depletion

Operator	<u>Rich Frank</u>	<u>4/4/84</u>	Inspector	<u>James Carpenter</u>
	Signature	Date		Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION  
Non Coal

OFFICIAL USE ONLY

INSPECTION REPORT

Date 7-16-84  
8-9

PERMITTEE The General Crushed Stone Co.	TOWNSHIP E. Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. 300733 Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date 12-31-84 Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Dfabase
- b. Highwall/s height/s: actual 250 ft. = 5 lifts  
bonded \_\_\_\_\_
- c. Length & Width of cut/s 1500 X 775 ft
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: 733-1

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: quarring

3. Equipment: Use & Condition SM 2

4. Contract Miner  yes  no Name: \_\_\_\_\_ Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

- 8. Previous Enforcement:
  - a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_
  - b. Adjudications Outstanding  yes  no Type \_\_\_\_\_
  - c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>Joseph Bronico</u> Signature	Title <u>of mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Investigator <u>Jonas Carpenter</u> Signature		<input checked="" type="checkbox"/> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 7-16-84

Permit Number <u>7974SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
---------------------------------	--------------------------------	------------------------

Name of Permittee  
The General Crushed Stone Co.

C. Comments & Recommendations

Sign posted

There has been no blasting -

Water in pit now app 75'

They have not did any quarrying in over 2 yrs -  
They still have material in stock which they  
are moving slowly -

I Found No STE Problems

Operator James Binner Signature 7/16/84 Date Inspector Jonas Carpenter Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

Non Coal  
**INSPECTION REPORT**

Date 11-2-84  
7-8

PERMITTEE The General Crushed Stone Co.	TOWNSHIP E. Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-84</u> Operational Status <u>ACTIVE</u>

**A1. GENERAL MINING INFORMATION**

a. Seams Diabase

b. Highwall/s height/s: actual 250 ft = 5 lifts  
bonded \_\_\_\_\_

c. Length & Width of cut/s 1500 X 775 ft.

d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0

e. Phase/s being mined: none

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition SAME

4. Contract Miner Name: \_\_\_\_\_  
 yes  no Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

8. Previous Enforcement:  
a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_  
b. Adjudications Outstanding  yes  no Type \_\_\_\_\_  
c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>GARRY TAYLER</u> Signature	Title <u>Co's Mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
<u>Garry V. Taylor</u>		Investigator <u>James Carpenter</u> Signature <u>45106</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

NONE

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 11-2-84

Permit Number <u>7974SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
Name of Permittee <u>The General Crushed Stone Co.</u>		

C. Comments & Recommendations

WATER IN PIT app 85' ± This means that  
2 levels will be under water soon?

There is still quite a bit of stone on  
storage pile.

Operator Larry Taylor 11/2/84 Inspector Jerry Carpenter  
Signature Date Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 7-24-86

PERMITTEE <u>The General Crushed Stone Co.</u> ADDRESS <u>STONE CO.</u> <u>P.O. Box 231</u> <u>EASTON, PA. 18042</u> <u>215-253-4271</u>	TOWNSHIP <u>E. ROCK HILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>		STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-76</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

a. Seams DIABASE

b. Highwall/s height/s: actual 250' - 5 LEVELS -  
bonded 101,700

c. Length & Width of cut/s 1500' x 775'

d. Total Acres: Permitted 103.2 (103.2) Affected ALL Regraded 0 Reclaimed 0

e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition F.E.L.  
Good

4. Contract Miner  yes  no  
Name: \_\_\_\_\_ Address: \_\_\_\_\_

5. Blasting at Site:  yes  no  
Contract Blaster  yes  no  
Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  yes  no  Active (describe)  Inactive

8. Previous Enforcement:  
a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_  
b. Adjudications Outstanding  yes  no Type \_\_\_\_\_  
c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>JOSEPH BRONICO -</u> Signature <u>Joseph Bronico - of</u>	Title <u>Off. Mg. V.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
Investigator <u>Jonas Carpenter</u> Signature _____		I.D. No. <u>44506</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

## INSPECTION REPORT

Date 7-24-86

Permit Number

7974 SM1

Township

E. ROCKHILL

County

BACKS

Name of Permittee

The General Crushed Stone Co.

## C. Comments &amp; Recommendations

The Crusher or Quarry operation AT  
THIS SITE HAS NOT OPERATED SINCE 1980.  
WATER CONTINUES TO ACCUMULATE IN PIT-  
3rd level over HALF FILLED-

They have Removed over 500 TON  
FROM STOCK THIS YEAR TO KEEP PERMIT  
ACTIVE-

There was A fault in Berm in Back  
of CRUSHING PLANT which was REPAIRED  
WHILE INSPECTION WAS CONDUCTED-

I.D. SIGN PASTED-

I FOUND NO PROBLEMS WHEN INSPECTION  
WAS COMPLETED

Operator

Jonas Carpenter  
Signature

7/24/86  
Date

Inspector

Jonas Carpenter  
Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 10-9-86

PERMITTEE <u>The General Crushed</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>STONE CO.</u>	TYPE OF INSPECTION	STATUS	LICENSE NO. <u>300733</u>
<u>P.O. Box 231</u>	Partial <input type="checkbox"/>	Violation/s Noted <input type="checkbox"/>	Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
<u>EASTON, PA 18042</u>	Followup <input type="checkbox"/>	Issue Order <input type="checkbox"/>	Expiration Date <u>12-31-86</u>
<u>215-253-4271</u>	Complete <input checked="" type="checkbox"/>	Cease Order Issued <input type="checkbox"/>	Operational Status
		Previous Violations not corrected <input type="checkbox"/>	

A1. GENERAL MINING INFORMATION

a. Seams DIABASE  
 b. Highwall/s height/s: actual 250' - 5 levels  
 bonded 101,700  
 c. Length & Width of cut/s 1500' x 775'  
 d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0  
 e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition F.E.L.  
GOOD

4. Contract Miner Name: \_\_\_\_\_  
 yes  no Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
 Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

8. Previous Enforcement:

a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_  
 b. Adjudications Outstanding  yes  no Type \_\_\_\_\_  
 c. Violations on Last Inspection  yes  no (if yes, explain status in remarks)

Person contacted <u>Joseph Bronico</u>	Title <u>Off. mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	ER-MR 5.2 attached.
Signature <u>Joseph Bronico</u>		Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
		No. of samples collected _____	
		Investigator <u>Jonas Carpenter</u>	<u>45706</u>
		Signature	I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the Investigator. The signature does not necessarily mean he agrees with the report.



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-9-86

Permit Number <u>7974 SMI</u>	Township <u>E. ROCKHILL</u>	County <u>BUCKS</u>
----------------------------------	--------------------------------	------------------------

Name of Permittee The General Crushed Stone Co

C. Comments & Recommendations

There has been NO MINING AT THIS SITE  
 SINCE LAST INSPECTION  
 WATER IN PIT RISING SLOWLY, APP 130' OF WATER  
 IN PIT -  
 I FOUND NO S+E PROBLEMS -  
 1 D SIGN POSTED.

Operator Joyce P. [Signature]      Date 10/9/86      Inspector Joyce Carpenter      Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 10-30-86

PERMITTEE <u>The General Crushed Stone Co. E. Rockhill</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042 215-253-4271</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input checked="" type="checkbox"/> Complete <input type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-86</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

a. Seams DIABASE  
 b. Highwall/s height/s: actual 250' - 5 levels  
 bonded 101,700  
 c. Length & Width of cut/s 1500' x 775'  
 d. Total Acres: Permitted 183.2 (183.2) Affected 183.2 Regraded 0 Reclaimed 0  
 e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: DRIFT MING

3. Equipment: Use & Condition FEL

4. Contract Miner  yes  no Name: \_\_\_\_\_ Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
 Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permt Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  yes  no  Active (describe)  Inactive

8. Previous Enforcement:

a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_  
 b. Adjudications Outstanding  yes  no Type \_\_\_\_\_  
 c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>VERNON R. SNYDER</u> Signature <u>Vernon R. Snyder</u>	Title <u>SAFETY DIRECTOR &amp; ENVIRONMENTAL ENG.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected <u>0</u> ER MR 5.2 attached.
Investigator <u>James Carpenter</u> Signature		<u>45102</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-30-86

Permit Number 7974SM1 Township E. ROCKHILL County BUCKS

Name of Permittee The General Crushed Stone Co.

C. Comments & Recommendations

MEETING WITH K. SNYDER, V. SNYDER, T. DEMASI ALLY OF  
GENERAL CRUSHED STONE TO DISCUSS OPERATION OF  
THIS MINE:

They STATE they will keep operation ACTIVE  
by removing a minimum of 500 TONS of MATERIAL  
Per year: Sec. # 2 of Act 219 - (ACTIVE OPERATIONS)  
& (MINERALS)

Operator Kenn R. Snyder 10/30/86 Inspector Jones Carpenter  
Signature Date Signature



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 2-25-87

Permit Number 7974SM1 Township EAST ROCKHILL County BUCKS

Name of Permittee The General Crushed Stone Company

C. Comments & Recommendations

This plant has NOT operated for  
years-

Water level in pit app 130' -

I found NO S + E problems -

The TOTAL AREA Covered by snow.

ID sign posted.

Operator [Signature]  
Signature

2/25/87  
Date

Inspector [Signature]  
Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 9-23-87

PERMITTEE <u>The General Crushed Stone Co.</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974 SM1</u>
ADDRESS <u>P.O. BOX 231 EASTON, PA 18042 215-253-4271</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-87</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

a. Seams DIABASE

b. Highwall/s height/s: actual 250' 5 LEVELS  
bonded 101,700

c. Length & Width of cut/s 1500' x 775'

d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0

e. Phase/s being mined: 793-5

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition FEL.

4. Contract Miner Name: \_\_\_\_\_  
 yes  no Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

8. Previous Enforcement:  
a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_  
b. Adjudications Outstanding  yes  no Type \_\_\_\_\_  
c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>GARY V. TAYLOR</u>	Title <u>F.C.M.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR 5.2 attached.
Signature <u>Gary V. Taylor</u>	Investigator <u>Janos Carpenter</u>	Signature <u>Janos Carpenter</u> I.D. No. <u>415016</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 9-23-87

Permit Number <u>7974SM1</u>	Township <u>EAST ROCKHILL</u>	County <u>TRUCKS</u>
Name of Permittee <u>The General Crushed Stone, Co</u>		

C. Comments & Recommendations

This mine has not operated in years  
 + there has been no blasting -  
 WATER LEVEL IN PIT HAS NOT CHANGED  
 IN MY OPINION:-  
 There is no problems with STE  
 Controls AT present:-  
 I D SIGN PASTED

Operator Larry Taylor Signature Date 9/23/87 Inspector Jonas Carpenter Signature

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 4-1-93

Mine Name ROCK HILL

INSPECTION REPORT  
NONCOAL

On Site Times AM -

Weather RAIN

PERMITTEE <u>GENERAL CRUSHED STONE Comp.</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BERKS</u>	PERMIT NO. <u>7994SM1</u>
ADDRESS <u>RD. 1 BOX 231 1609 SULLIVAN TRAIL EASTON, PA 18042</u>	VIOLATION HISTORY <u>0 NOV'S 0 CO'S</u>	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> <u>300</u> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>733-12-31-93</u>	
		OPERATIONAL STATUS <u>ACTIVE</u>	

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500' x 900' x 250'-511FTS OPEN PIT QUARRY TOP 850  
W.T 510  
BOT 464

b. Acreage (total): Bonded 103.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: FEL

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil Rem/Sto/Handng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spail					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
<input checked="" type="checkbox"/>	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: WATER NOW COVERS ALL BENCHES - DEPT ?

NOTHING AFFECTED  
NO PROBLEM FOUND

Person Contacted <u>MIRIAM ELGINAY</u>	Title <u>OFFICE</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Miriam Elginay</u>	Investigator Signature & I.D. No. <u>James Carpenter</u> <u>4506</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
	Range of Samples Collected _____ to _____	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 6-15-93

Mine Name ROCK HILL  
Weather Clear

INSPECTION REPORT  
NONCOAL

On Site Times Am -

PERMITTEE <u>The General Quarried Stone Co. E. Rock Hill</u>	TOWNSHIP <u>BUCKS</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745m1</u>
ADDRESS <u>P.O. BOX 231 EASTON, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
			LICENSE NO. & EXP. DATE <u>300733-12-31-93</u>
			OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal  Small Noncoal  Complete  Partial or Followup

a. Areas-Minerals-Pit Dimensions (LWM)-Method: 1500'x900'x250'-5 LIFTS  
OPEN PIT QUARRY

b. Acreage (total): Bonded 103.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: FEL

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) None

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndlg					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					<input checked="" type="checkbox"/> 745 Support Facilities			
	708 Treatment Facilities					<input checked="" type="checkbox"/> 749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds					<input checked="" type="checkbox"/> 753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					<input checked="" type="checkbox"/> 761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO ONE ON SITE

Nothing Affected

Person Contacted <u>Copy office</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Copy office</u>	Investigator Signature & I.D. No. <u>Jonas Computer</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 0 <input type="checkbox"/> 6

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 8-20-93

Mine Name ROCK HILL  
Weather FOGGY

INSPECTION REPORT  
NONCOAL

On Site Times AM-

PERMITTEE <u>The GENERAL CRUSHED STONE CO</u>	TOWNSHIP <u>E ROCK HILL</u>	COUNTY <u>-BUCKS</u>	PERMIT NO. <u>79749M1</u>
ADDRESS <u>P.O. BOX 231 16055 MILL VALLEY TRAIL EASTON, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>300737-12-31-93</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500' X 900' X 250' 5 LIFTS OPEN PIT QUARRY</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 103.2 Affected ALL Regraded 0 Reclaimed 0  
c. Equipment-Use & Conditions: FRI

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NO

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Handng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: WATER IN DRAINAGE HAS RASED @ LEAST 5' or MORE -

NO PERMIT PROBLEM OBSERVED

Person Contacted <u>MIRIAM ELGINOFFICE</u>	Title	Discharge/Saaps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>McGinty</u>	Investigator Signature & I.D. No. <u>Jonas Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<u>4 5 0 6</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Mine Name ROCK HILL  
Weather CLEAR

INSPECTION REPORT  
NONCOAL

Date 10-25-93

On Site Times Am -

PERMITTEE <u>THE GENERAL CRUSHED STONE COMPANY</u>	TOWNSHIP <u>E. ROCK HILL</u>	COUNTY <u>BERKLEY</u>	PERMIT NO. <u>74745M1</u>
ADDRESS <u>P.O. Box 231 1609 SULLIVAN TRAIL EASTON, PA - 18042</u>	VIOLETION HISTORY <input type="checkbox"/> NOV'S <input type="checkbox"/> CO'S	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: <input type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> <u>506733-12-31-93</u> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>33-12-31-93</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500 X 750 X 250 - 5 LIFTS OPEN PIT OPERATING</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 103.2 Affected ALL Regraded  Reclaimed

c. Equipment-Use & Conditions: KEC

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Handling					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures					<input checked="" type="checkbox"/> 745 Support Facilities			
	708 Treatment Facilities					<input checked="" type="checkbox"/> 749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds					<input checked="" type="checkbox"/> 753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					<input checked="" type="checkbox"/> 762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO PROB ON SITE  
WATER up 1002'  
NO PROBLEM OBSERVED

Person Contacted	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
Signature	<u>Copy Made @ Office</u>	Investigator Signature & I.D. No. <u>James Conarty</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 2-3-95

Mine Name ROCK HILL  
Weather SUNNY

INSPECTION REPORT  
NONCOAL

On Site Times: 1 hr

PERMITTEE <u>The General Crushed Stone Co.</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>PO BOX 231 1629 SULLIVAN TRAIL EASTON, PA 18042</u>	VIOLETION HISTORY ____NOV'S ____CO'S	VIOLATIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> <u>306</u> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal _____ Complete <input checked="" type="checkbox"/> Partial or Followup _____		LICENSE NO. & EXP. DATE <u>733-12-31-95</u>	
a. Areas Minerals-Pit Dimensions (L/W/H)-Method: <u>1500x900x250-5 LIFTS OPEN PIT QUARRY</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 104.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					748 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacment					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED AT R.R.-  
NO ONE ON SITE-  
TRUCKS & CON'S. EQUIPMENT PARKED 24(20)

Person Contacted <u>Copy FILE</u>	Title	Discharge/Scops <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Copy</u>	Investigator Signature & I.D. No. <u>Juanes Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<u>4506</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill  
Weather Cloudy

INSPECTION REPORT  
NONCOAL

Date 4-7-95

On Site Times 1 hr

PERMITTEE <u>The General Crushed Stone</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974SM</u>
ADDRESS <u>P.O. BOX 231</u>	VOLATION HISTORY <u>NOV'S</u> <u>CO'S</u>	VIIATIONS NOTED PREVIOUS VIOLATIONS: <u>CORRECTED</u> <u>UNCORRECTED</u>	LICENSE NO. & EXP. DATE <u>700 821-12-81-95</u>
<u>ERSTON PA 18042</u>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>		OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal  Small Noncoal  Complete  Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500 X 900 X 250 - 5 LIPS  
OPEN PIT QUARRY

b. Acreage (total): Bonded 104.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil Rem/Sto/Handing					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Farming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED - EQUIPMENT PARKED AND SITE

NO ONE ON SITE

Person Contacted <u>C. J. ...</u>	Title <u>MAINTENANCE</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>C. J. ...</u>	Investigator Signature & I.D. No. <u>James ...</u>	Range of Samples Collected _____ to _____	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Mine Name ROCK HILL  
Weather Sunny

INSPECTION REPORT  
NONCOAL

Date 5-22-95

On Site Times Am

PERMITTEE <u>The GENERAL Crushed Stone Company</u>	TOWNSHIP <u>E Rockhill</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974 Sm1</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER <u>300</u> FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>			LICENSE NO. & EXP. DATE <u>733-12-31-95</u>
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500x900x250-561 FFS OPEN PIT QUARRY</u>			OPERATIONAL STATUS <u>ACTIVE</u>

b. Acreage (total): Bonded 104 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) None

PERFORMANCE STANDARDS NONCOAL									
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO PROB. ON SITE  
WATER IN PIT RISING  
NO PROBLEM OBSERVED

Person Contacted	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Copy of SCE</u>	Investigator Signature & I.D. No. <u>James Carpenter</u>	Range of Samples Collected _____ to _____	<input type="checkbox"/> 4 <input type="checkbox"/> 8 <input type="checkbox"/> 16

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 9-12-95

Mine Name ROCK HILL  
Weather SUNNY

INSPECTION REPORT  
NONCOAL

Or Site Times AM

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BLUES</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>			LICENSE NO. & EXP. DATE <u>206733-12-31-95</u>
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500x900x250-5 LIFTS OPEN PIT QUARRY</u>			OPERATIONAL STATUS <u>ACTIVE</u>

b. Acreage (total): Bonded 104 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner  yes  no      e. Blasting at Site  yes  no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Handing					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED AT RR  
NO ONE ON SITE  
NO PROBLEM OBSERVED

Person Contacted <u>[Signature]</u>	Title <u>[Signature]</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>[Signature]</u>	Investigator Signature & I.O. No. <u>[Signature]</u>	Range of Samples Collected _____ to _____	<u>4</u> <u>5</u> <u>0</u> <u>6</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 12-31-97

Mine Name Rock Hill  
Weather RAIN

INSPECTION REPORT  
NONCOAL

On Site Times: AM -

PERMITTEE <u>The General Crushed Stone Co</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 Peston, PA 18042</u>	VIOLATION HISTORY NOV'S CO'S	VIOLATIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>300733-12-31-95</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500x900x 250-5 LIFTS ORP</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 104 Affected ALL Regraded Reclaimed

c. Equipment-Use & Conditions: SAME

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sta/Hp/dng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE AT RR LOCKED  
NO ONE ON SITE

Person Contacted <u>Cam</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no
Signature <u>Copy to</u>	Investigator Signature & I.D. No. <u>Jonas Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<u>4506</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Date 1-5-96

Mine Name ROCK HILL  
Weather Snow Covered

INSPECTION REPORT  
NONCOAL

On Site Times AM

PERMITTEE <u>The General Creek Company</u>	TOWNSHIP <u>E. Rock Hill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7945M1</u>
ADDRESS <u>P.O. Box 23</u> <u>Easton PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>30075-1231-96</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500 x 900 x 250-5455</u> <u>5 P P</u>		OPERATIONAL STATUS <u>Active</u>	

b. Acreage (total): Bonded 104 Affected ALL Regraded \_\_\_\_\_ Reclaimed \_\_\_\_\_

c. Equipment-Use & Conditions: JAMP

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) None

PERFORMANCE STANDARDS NONCOAL					PC or Reg	Viol.	Comp. Date		
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	748 General Safety			
	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS:  
No one on site  
Entrance Road covered by over 2' of undisturbed snow

Person Contacted <u>Jay M.</u>	Title	Discharge/Slops <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Jay M.</u>		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		Investigator Signature & I.O. No. <u>Jonas Carpenter</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry  
Weather raining - cold  
(610) 253-4271

INSPECTION REPORT  
NONCOAL

Date 12/11/96

On Site Times - PM

PERMITTEE <b>Milestone Materials, Inc.</b>	TOWNSHIP <b>East Rockhill</b>	COUNTY <b>Bucks</b>	PERMIT NO. <b>79745MI</b>
ADDRESS <b>P.O. Box 231 1900 Sullivan Trail Easton, PA. 18044</b>	VIOLATION HISTORY <u>0</u> NOV'S <u>0</u> CO'S	VIOLATIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>			LICENSE NO. & EXP. DATE <b>3-00679 9/30/97</b>
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>Dipbase - open pit quarry</u> <u>~1500ft x 900ft x ~250ft ± - 5 lifts</u>			OPERATIONAL STATUS <b>Active ??</b>

b. Acreage (total): Bonded (103.2) 103.2 Affected ~103.2 Regraded — Reclaimed —  
c. Equipment-Use & Conditions: To be determined

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) (To be determined)

PERFORMANCE STANDARDS NONCOAL									
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
✓	700 Unauthorized Mining					730 Concurrent Reclamation			
✓	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil Rem/Sto/Handlg					735 Revegetation			
✓	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities				✓	749 General Safety			
	708 Sedimentation Ponds				✓	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					758 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
✓	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: I.D. sign is posted. Site entrance has gate locked. No one is on site. Garage, scalehouse, and other buildings are boarded closed. This site has not been worked since 1991-2 as determined from past inspection reports. Inspector will contact the Operator to verify that a minimum of 500 tons of material has been removed from site in order to retain an active status. Water monitoring reports are up-to-date. There is no violation history for the past 2 years.

Person Contacted <u>Copy to be mailed</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no ?
Signature	Investigator Signature & I.D. No. <u>John Embick</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no ?
		Range of Samples Collected _____ to _____
		4 5 0 5

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

