January 4, 2018

Hanson Aggregates Pennsylvania, Inc. Attn: Mr. Mark Kendrick, P.E., Vice-President 7660 Imperial Way Allentown, PA 18195 JAN 10 2018

East Rockfill Township

Re:

Asbestos Testing at Rock Hill Quarry

SMP No. 7974SM1

East Rockhill Township, Bucks County

Dear Mr. Kendrick:

It has come to the Department's attention that asbestos form materials may be present in the rock planned to be mined at the quarry. Therefore, the Department requires a comprehensive investigation, by experienced professionals, to determine if asbestos form minerals are present in any of the rock planned to be mined at the Rockhill quarry. This comprehensive investigation shall include a detailed plan describing how the rock will be tested and surveyed to make the asbestos review and/or determination. The plan shall include the locations of each sample site, drill log, depth of hole(s) and any other pertinent information regarding the testing procedure. All of this information and results of the testing shall then be submitted to the Department.

At this time, and until further notice, all production drilling, blasting and crushing activities are ceased at the Rockhill quarry. The Department will review the results of the testing and determine if production, drilling and crushing activities may resume.

Sincerely,

Michael J. Menghini

Michael J. Menghini

District Mining Manager

Bureau of District Mining Operations

cc:

John Stefanko

William Plassio

Michael Kutney

Gary Latsha

Amiee Bollinger

Ross Klock

James Rebarchak

Sachin Shankar

East Rockhill Township

Bucks County

File

MS1-Han (1-18) MJM:MK:dp