



RECEIVED

DEC 23 2019

East Rockhill Township

December 18, 2019

Hanson Aggregates Pennsylvania LLC
Attn: Mr. Andrew Gutshall, P.G., Environmental Manager
7660 Imperial Way
Allentown, PA 18195-1040

Re: Rock Hill Quarry Naturally Occurring Asbestos Sampling
SMP No. 7974SM1
East Rockhill Township
Bucks County

Dear Mr. Gutshall:

On September 20, 2019, the Department sent a letter requesting additional testing and analysis for asbestos in aggregate and water at the Rock Hill quarry. To date, the Department has not received the information requested. The following information is required for the Department to evaluate the environmental, health and safety risks at the Rock Hill quarry:

1. Please conduct Transmission Electron Microscopy using EPA method 600/R-93/116 (or equivalent) analysis for asbestos on all rock samples collected at the Rock Hill quarry.
2. Please prepare suitable samples for petrographic analysis.
3. Please resample at all the water sampling locations using EPA method 100.1.

This information is due to the Pottsville Office by January 20, 2020.

Sincerely,

A handwritten signature in black ink that reads "Gary A. Latsha".

Gary A. Latsha
District Mining Manager
Bureau of District Mining Operations

cc: John J. Stefanko, Deputy Secretary
Daniel Sammarco, Director DMO
Michael Kutney, P.G., EGM
Craig Lambeth, Office of Chief Counsel
Amiee Bollinger, SMCI
Sachin Shankar, SERO
James Rebarchak, SERO
Robert Fogel, CRRC DEP
Virginia Cain, SERO
Marianne Morano, East Rockhill Township Manager
Rockhill Environmental Preservation Alliance
County of Bucks
File
MS1-Hanson (12.19)

GAL:cmb